Before you begin



Enhance your assembly experience.

Download the free BILT app for 3D step-by-step instructions.












This guide will show you how to install your new Wilco Off-road ADV Trail Boss Complete Kit.




To complete this installation, you will need the following tools. 10, 15, 17, and 19 millimeter Box Wrenches, Adjustable Wrench, Socket Wrench with 10, 15, 17 and 19 millimeter Sockets, Safety glasses and a Torque Wrench. It is recommended that you lay out all the parts and tools prior to beginning.












Attach the passenger side Corner Brace by first mounting it to the cab Bedrail Clamp Plate and then to the Passenger Side Riser Weldment. Do not fully tighten the nuts and bolts at this point.




Attach the driver side Corner Brace the same way. Do not fully tighten the nuts and bolts at this point.




You may want to place a Blanket or some other protective cover over the roof of your truck to prevent any damage.



Place the Driver Side Frame Weldment to the Driver Side Riser Weldment. Attach the top M10 by 1.5 by 90 Hex Screw, M10 Washers and M10 Lock Nut first. Next, attach the lower bolt, washers and nut. Do not fully tighten the nuts at this point.




Attach the Passenger Side Frame
Weldment to the Passenger Side Riser
Weldment the same way. Insert the top
bolt and washers first, and then the lower
bolt and washers. Do not fully tighten the
nuts at this point.




Place the Tire Support Rack between the Frame Weldments as it will not fit once they are connected. Place the Horizontal Connecting Tube over each of the Frame Weldments. There should be enough play in each of the Riser Weldments and Frame Weldments to fit the Horizontal Connecting Tube with ease.




Place the Fairing onto the Horizontal Connecting Tube and insert the (4) Carriage Bolts.





Place the Light and Hooking Bracket to the underside of the Horizontal Connecting Tube ensuring the correct orientation. Attach the brackets using (4) M10 Lock Nuts and M10 Washers.




Attach the Bumper to the Driver Side Frame Weldment.











Place a Highrider Tube assembly onto the Driver Side Lowrider Weldment and the Driver Side Riser Weldment. Attach it to the Lowrider Weldment using an M10 by 60 Screw, (2) M10 Washers and an M10 Lock Nut. Do the same for the Passenger Side Lowrider Weldment.


Attach the Highrider Tube to the Driver Riser Weldment using an M10 by 25 Bolt. Do the same for the Passenger Side Riser Weldment.



Place the Driver Expedition Panel between the Driver Side Riser Weldment and the Driver Side Highrider Tube. Attach to the Riser Weldment using (2) M10 by 1.5 by 30 Screw, an M10 Washer and an M10 Lock Nut. Do the same for the Passenger Side Expedition Panel.




Attach the Expedition Panels to the Highrider Tubes using (2) M10 by 80 Screws, (4) M10 Washers and (2) M10 Lock Nuts.




The passenger's side should be completed along with the driver's side


Hook one of the Turnbuckles into the hole on the Passenger Bedrail Weldment as shown. Adjust the Turnbuckle by turning the body of the Turnbuckle. Once set with moderate pressure on the D hook of the truck bed, tighten both Jam Nuts on the Turnbuckle.




Place the Turnbuckle on the Driver Bedrail Weldment in the same way.




There are numerous locations to mount the Racking Tubes onto your ADV Trail Boss Complete Kit.



To attach the Racking Tubes, first place a Crossbar Clamp Assembly onto a Tube as shown.





Make sure that the rack is straight and everything is properly placed. Check all the connections to make sure everything is tight. Torque the remaining bolts in order:

Riser Bolts/Nuts: 80 foot-pounds. Corner Braces: 45 foot-pounds. Crosstube, Rear: 45 foot-pounds. Clamp Blocks: 35 foot-pounds. Crosstube, Front: 40 foot-pounds. Racking Tubes: 40 foot-pounds.

